

# QUALITY DOCUMENTS

W.I. NUMBER 09

# INVIGILATOR TRAINING PROGRAMME



This document forms an integral part of the Company Quality system, and adherence to the requirements specified within are mandatory upon all Company personnel and upon any subcontractor required to work in accordance with it.

This is a controlled document and must not be altered in any way without authorisation from the Company Quality Manager.

Issued by:

Title: Quality Manager

Date: 01.01.16

Authorised / Approved by:

Title: Co-Managing Director

Date: 01.01.16



#### DOCUMENT AMENDMENTS AND UPDATES

Date	Section	Amendment made	Name of person
Amended	Amended		inserting change
01.01.16		Numerous changes have been made to this document	S. Young

All changes are hi-lighted Copies of this document are sent to PCN/BINDT.

## **CONTENTS**

1	Scope
2	Responsibilities
3	Definitions
4	Applicable Documents
5	Procedure
6	Invigilation – EN4179/NAS410/SNT Examinations
Appendix 1	Invigilator Training Programme Front Sheet
Appendix 2	Signed Invigilator Statement
Appendix 3	Invigilator Check List
Appendix 4	General, Theory & Practical Facilities & Methods Check Lists
Appendix 5	Points to be Observed During Practical Examinations
Appendix 6	Extract from QP4 sections 7, 17, 22 & 23



#### 1.0 SCOPE

1.1 This Work Instruction details the Invigilator Training Programme adopted by Lavender International in order to conform to PCN requirements. All such personnel are listed on the PCN Test Centre Authorisation Schedule.

#### 2.0 **RESPONSIBILITIES**

- 2.1 The Quality Manager is responsible for:
  - a) Ensuring this Training Programme is followed for the training of all Examination Invigilators used by Lavender International.
  - b) Maintenance of all records relating to these exercises.
  - c) Agreeing the form of any corrective actions that may be necessary arising from these processes (in association with the TCCE).
  - d) For ensuring that all currently used Invigilators are correctly listed on the PCN Test Centre Authorisation Schedule.

#### 3.0 DEFINITIONS

3.1 See the definition of an Invigilator in CP9 section 2.8.

#### 4.0 APPLICABLE DOCUMENTS

- 4.1 The latest issues of:
  - a) PCN/GEN General Requirements for NDT
  - b) Lavender International Quality Procedure QP4 Control and Administration of Personnel examinations
  - c) Lavender International Quality Procedure QP6 Control of Nonconformance, Corrective Action and Preventive Action
  - d) CP9 Requirements for BINDT Authorised Qualifying bodies
  - e) PSL56 Commitment to confidentiality and impartiality
  - f) Curriculum Vitae of invigilator
  - g) Lavender International Quality Procedure QP5 series of procedures Health and Safety

#### 5.0 PROCEDURE

5.1 This document is designed to address the PCN requirements of CP9 where Examination Invigilators shall either hold relevant level 2 certification or shall have undergone appropriate training to cover points to be observed and recorded during practical examinations.



- 5.2 Persons not holding relevant level 2 certification shall have been trained by an appropriate level 3 to the comprehension of the following points related to PCN examination requirements.
- 5.3 All persons acting as Examination Invigilators on behalf of Lavender International NDT Ltd shall have been formally inducted to this programme. Exemptions shall only apply to the method sections where the invigilator holds at least level 2 in the appropriate method. This shall be indicated by ticking the box adjacent to the method heading.
- 5.4 The Examination Invigilator Training Programme and records consists of five (5) parts:
  - Appendix 1 Invigilator Training Programme Front Sheet (signed by an appropriate L3)
  - Appendix 2 Signed Invigilator Statement
  - Appendix 3 Invigilator Check List
  - Appendix 4 General, Theory and Practical facilities & Methods
  - Appendix 5 Points to be Observed during Practical Examinations for the following NDT Techniques:-
    - 5.1 MT
    - 5.2 PT
    - 5.3 UT
    - 5.4 RT/RI
    - 5.5 ET
    - 5.6 VT/WI
    - 5.7 TOFD
    - 5.8 PA
    - 5.9 ACFM
  - 5.5 The following records (which are considered self-explanatory) shall be completed and be maintained for all Examination Invigilators used by Lavender International. Only the sections applicable to the methods applied for shall be provided and completed.
- 5.6 These documents, signed by the relevant Level 3 Tutor, shall confirm that the nominated Invigilator can fulfil the requirements of a PCN Invigilator.
- 5.7 Upon completion of the Invigilation training programme a copy of Appendices 1-4, signed PSL56 and the individual invigilator's CV are sent by the Quality Manager to PCN for addition to the PCN Test Centre Authorisation Schedule.





PCN will then amend the PCN Test Centre Authorisation Schedule and send an updated copy to us.

#### 6.0 INVIGILATION – EN4179/NAS410 EXAMINATONS

- The training programme for invigilation of exams other than PCN is detailed in WI 09A. This is normally only applicable to certain companies served by Level 3 Outside Agency personnel where such training and approval is required by the Prime Contractor.
- 6.2 In these circumstances the following documents would not be required to be completed and PCN are not notified:
  - PSL56
  - CV
- 6.3 Appendices 1-5 are completed and signed as appropriate. Copies are retained by the Quality Manager.



# INVIGILATOR TRAINING PROGRAMME FRONT SHEET (WI 09 pages 7-41 form the Invigilator Training Programme)

INVIGILATOR NAME:	
TRAINED BY:	
SIGNATURE OF L3:	
DATF:	



## **SIGNED INVIGILATOR STATEMENT**

	, of od the following documents and a behalf of Lavender International <sup>-</sup>	, have received, read m prepared to act as an appointed Test Centre.
All information	n relating to this appointment will	remain totally confidential.
a.	QP4 – Control and Administration 17, 22 & 23 (Appendix 6 of this do	of Personnel Examinations sections 7, ocument)
b.	WI 09 – Invigilator Programme	
c.	QP5 series of documents – Health	and Safety (as applicable)
Name in Full: (Capital Lette		
Signed:		
Date:		



## **INVIGILATOR CHECK LIST**

General	Room – quiet, clean, well lit	
	Exam requirements clear	
	Calculator – non-programmable (if applicable)	
	Cheating instructions given out verbally	
	No training material visible	
Theory	Satisfactory separation of candidates	
	Exam paper only on table	
	Check level of papers	
	Check method of papers	
	Check time limit	
Practical		
Samples	Check instruction sheet completed	
	Check samples	
	Check equipment/consumables	
	Check sample report forms	
	Check time limit	
Instruction	Check instruction sheet	
	Check samples	
	Check standards available	
	All notes to be left by candidate	
Health & Safety	Check relevant notices displayed and complied with	
	AWAY COURSE/EXAM CHECK LIST	
Adequate classroom	facilities	
Adequate practical fa	acilities	
Adequate teaching a	ids (as appropriate)	
Test samples – provided by Lavender International		



## **GENERAL, THEORY & PRACTICAL FACILITIES & METHODS CHECK LISTS**

1.0	<u>GENERAL</u>	
	ITEM	IS CHECKED
1.1	Familiarity with PCN documents and method appendices.	
1.2	Familiarity with time allowed per paper or specimen.	
1.3	Ensure that no examination material is removed from the examination area.	
1.4	Ensure that all documents produced by the candidate are placed in the examination folder without discussion.	
1.5	Ensure that at no time during the examination the candidate is unsupervised.	eft
1.6	Ensure that use of mobile phones is prohibited at all times during any part of PCN examinations.	
2.0	THEORY EXAMINATION FACILITY  ITEMS CHE	CKED
2.1	Assess the facility to satisfy that the room is clean, quiet, suitably illuminated and is adequately heated and comfortable.	
2.2	Ensure that candidates are seated at least 1.5 metres apart.	
2.3	Check that calculators are not programmable and that the candidate has not hidden crib sheets or written notes in or on the calculator case.	
2.4	Ensure that no talking between candidates occurs.	
2.5	Ensure that only the examination material permissible is on the table during the exam.	





2.6	Do not allow any candidates to leave the room during the completion of any examination paper.	
3.0	PRACTICAL EXAM FACILITY	
3.1	Ensure that the work area conforms to the Health & Safety Regulations (refer to Lavender International QP5)	
3.2	Ensure that any equipment supplied by the test centre is not damaged and is within the calibration period stated on the calibration label.	
3.3	Ensure that all consumables required for the examination are available - including cleaning substances and clean tissues or cloths for restoration of surface after testing.	
3.4	Safety data cards for all consumables shall be made available for candidates to access during practical work.	
3.5	Candidates are not permitted to discuss any element of their examination with other candidates during examination conditions.	





## 4.0 METHODS/TECHNIQUES

l.1	M	lagnetic Particle Methods H	lolds	Level	2	]		
		he following items of equipment shall be check vailability prior to the examination:	ed b	y the	invigila	ator to	ensi	ure
				ITE	MS CHI	CKED	)	
	•	AC Yoke						
	•	Coils (AC and/or DC)						
	•	Bench unit with current flow & magnetic flow or r	igid d	coil				
	•	Prod unit when applicable to a required technique	<u>.</u>					
	•	Flux Indicators						
	•	Residual Field Meters						
	•	Settlement Flask						
	•	Photometer						
	•	Radiometer						
	•	Filtered UVA black light source						
	•	White Light Source						
	•	4.5kg test Weight						
	•	BS6072 type TP1 current flow test sample						
	•	BS6072 type TP4 magnetic flow test sample						
	•	White contrast paint						
	•	Black ink solution and suitable means of application	on					





## 4.1 Magnetic Particle Methods Continued

	TIEMS	S CHECKED
•	Fluorescent ink solution and suitable means of application	
•	Dry powder and suitable means of application	
•	Test area that can be controlled to achieve a maximum white light level of 20 lux when fluorescent inspections are required	
•	Verify that all consumables such as inks, paints, powders and solvents are within their expiry date and that batch numbers, where applicable are clearly visible.	
•	Verify that the filter on the UV-A source is	



4.2	Liquid Penetrant Methods	Holds Level 2	
	The following items of equipment shall be availability prior to the exam:	checked by the invigilator to	) ensure
	White light source	ITEMS CHECKED	
,	Filtered UVA black light source		
,	Radiometer		
,	Photometer		
,	Tam Panels		
,	Aluminium Comparator Blocks		
,	Refractometer		
,	• Water wash station		
,	Drying cabinet		
,	Colour contrast penetrant		
,	Fluorescent penetrant		
,	Emulsifier		
,	Developer		
,	• Viewing area that can be controlled to a max of 20 lux white light	ximum	
,	<ul> <li>Verify that all consumables such as solvents, and developing powders are within their exp and that batch numbers, where applicable a clearly visible.</li> </ul>	piry date	
,	Verify that the filter on the UV-A source intact and is not damaged, broken or co	<u> </u>	





4.3

**Ultrasonic Methods** 

The following items of equipment sha availability prior to the exam:	II be checked	by the invigilator	to ensure
атопасто, ретог со ато стани		ITEMS CHECKE	D

Holds Level 2

•	"A" Scan Ultrasonic Set	
•	Battery Charger	
•	A selection of 0°, 45°, 60° & 70° Probes.	
•	Suitable cables to connect the probes to the UT set.	
•	A2, A4, A5 & A6 Calibration Blocks	
•	3mm diameter side drilled hole DAC block/s	
•	3mm Flat bottomed hole DAC block/s	
•	Couplant	
•	Beam Spreads & Measuring Equipment.	
•	Chinagraph pencils for temporarily marking on metal surfaces.	



4.4 Ra	diographic Testing	Holds Level 2
	igilators for radiographic testing shall ic radiation safety certification	hold current
	The following items of equipment shall be check prior to the exam:	ked by the invigilator to ensure availability
	prior to the exam.	ITEMS CHECKED
	X ray set including control panel	
	Gamma source with wind-out mechanis	sm.
	Survey meter	
	Film Badge	
	IQIs/Penetrameters	
	• Lead idents	
	Lead tape	
	Dark room and film processing equipm	ent
	• Safe lights	
	Selection of radiographic film	
	Radiograph viewer with high & low interest.	ensity lamps.
	<ul> <li>Viewing area with a controlled maximu white light level.</li> </ul>	ım 10 lux
	Densitometer.	
	Calibration strip to assess densitometer	r.
	Low power magnifier.	
	Measuring Equipment.	





4.5	Radiographic Interpretation Hole	ds Level 2
	Radiograph viewer with high & low intensity lan	nps.
	<ul> <li>Viewing area with a controlled maximum 10 lux white light level.</li> </ul>	
	Densitometer.	
	Calibration strip to assess densitometer.	
	Low power magnifier.	
	Measuring Equipment.	





4.6	Eddy Current Methods	Holds Level 2
	The following items of equipment shall be availability prior to the exam:	checked by the invigilator to ensure

		ITEMS CHECKED
•	Phase display instrument	
•	Battery Charger	
•	Selection of test coils	
•	Selection of balance loads	
•	Connecting cables to suit coils and test instrument	
•	Ferrous & non-ferrous slotted reference blocks	
•	Non-conductive shims	
•	Aluminium foil	
•	Chart recorder & spare paper ( tubes only )	
•	Roll of masking tape	
•	Roll of PVC tape	
•	Measuring equipment	
•	Protractor	





4.7	Visual Testing / Weld Inspection Methods	Holds Level 2
	The following items of equipment shall be checked availability prior to the exam:	by the invigilator to ensure
		ITEMS CHECKED
	Low power magnifier	
	• High power magnifier (10 to 20X )	
	Adjustable light source	
	• Torch	
	Selection of mirrors	
	Rigid Boresope	
	Measuring equipment	
	Welding gauges	
	<ul> <li>Photometer</li> </ul>	



4.8	Time	of Flight Diffraction	Holds Lev	el 2			
		ollowing items of equipment shall	be checked	by the	invigilator	to	ensure
	avallal	bility prior to the exam:	ITE	MS CHE	CKED		
	•	System Control and Functional Che	cks		]		
	•	Verification of equipment settings			]		
	•	Setting up the NDT apparatus					
	•	Performance of test					
	•	Pre and post test					
	•	Integrity of data: coupling, PRF, ga	ting		]		
	•	Position and direction of encoder					
	•	Contrast achieved					
	•	Production of the test report					



4.9	Phase	ed Array	Holds Lev	el 2		
		ollowing items of equipment shall	be checked	by the	invigilator	to ensure
	availability prior to the exam:			ITEMS CHECKED		
	•	System Control and Functional Chec	cks			
	•	Verification of equipment settings				
	•	Choice of array frequency and design	jn			
	•	'A' scan collection parameters				
	•	Method of setting equipment gain				
	•	Performance demonstration/calibrat	tion			
	•	Test Report				





4.10	Alternating Current Field Measurement Holds	Level 2
	The following items of equipment shall be checked by availability prior to the exam:	by the invigilator to ensure
		ITEMS CHECKED
	ACFM instrument	
	<ul> <li>Power supply</li> </ul>	
	<ul> <li>Selection of probes</li> </ul>	
	Calibration sample	

• Computer with software

• Measuring equipment



#### POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS

#### **METHOD 5.1 - MAGNETIC PARTICLE TESTING**

#### 1.1 System control and functional checks

System control and functional checks will usually include predetermined checks, each being allocated a share of the maximum marks (for example, measurement of magnetic ink solids content, use of CF and FF test pieces etc.)

#### 1.2 Verification of equipment settings

Verification of settings will involve the candidate carrying out predetermined checks to give/demonstrate confidence in the ability of the technique to detect discontinuities in the range sought (for example, use of portable flux indicators, field strength meter; viewing conditions – white light and UV(A) radiation assessment etc.).

#### 2.1 Preparation of the test piece

Surface preparation – pre-cleaning, contrast aid paint.

#### 2.2 Technique selection (level 2)

Selection of magnetisation techniques to provide complete coverage with respect to geometry of specimen; selection of current or flux values; UV or white light.

#### 2.3 Setting up the NDT apparatus

Preparation of portable and fixed units, prods, electromagnets, coils, contact heads; avoidance of fire hazards, correct ventilation, safe use of toxic materials and UV(A) radiation.

#### 2.4 Performance of test

Correct application of field and detecting media with respect to the application of magnetisation; optimisation for detection of expected discontinuities.

#### 2.5 Post test procedures

Preservation and/or recording of indications; demagnetisation; cleaning.

#### 3.1 Detection of mandatory reportable defects

Detection of all reportable defects will normally attract maximum marks. However, missing one reportable defect (out of, for instance, a total of three in a specimen) will *normally* attract a mark of zero for detection and a commensurate reduction in



the remaining marks such that the candidate will fail that specimen, since it follows that characterisation, positioning and sizing cannot be carried out for a non-reported defect. A candidate failing one specimen <u>may</u> still achieve at least 70% for the practical part if sufficiently high marks are attained in all other specimens.

Examination centres will provide candidates with a code, specification or standard, or a locally devised instruction on reporting thresholds for each specimen.

#### 3.2 Characterisation

Within the limitations of the NDT method, recording the nature of discontinuity detected (surface and sub-surface where applicable); its position and dimensions.

The candidate is expected to correctly state the nature of the reported indication. Candidate instructions will clarify what is expected in this respect, e.g. whether a simple description (volumetric or planar; crack-like indication) or a fuller description (fatigue crack; lack of sidewall fusion; cold shut; stress corrosion cracking) is required.

The candidate will be expected to accurately report the position of the reported indication with respect to a given datum by giving two dimensions longitudinal and transverse for surface methods and three dimensions length, through thickness and depth for volumetric methods.

Defect dimensions must be correctly reported with the tolerance defined in the master report. The tolerance allowed will depend upon the NDT method/technique and type/position of defect.

#### 3.3 Level 2 evaluation against acceptance criteria

Off-line data analysis procedures for digital/computerised instruments.

Correct interpretation of procedure, code, standard or specification.

#### 3.4 Production of the test report

All pertinent information is reported in writing or as computerised data.

The candidate failing to report a discontinuity specified on the specimen master report as 'mandatory for candidates to report' when performing the test in the conditions specified in the master report will be awarded zero marks for section 3 of the practical examination related to the specimen tested.

Non-reportable defects. The candidate will not be penalised for reporting a non-mandatory reportable discontinuity which does exist in the specimen. However, falsely reporting as a defect an indication which does not actually exceed the reporting threshold will be penalised. Examiners may use discretion in this but, where discretion is applied, the examination must be moderated.

<u>Non-existent defects</u>. The number of marks awarded for detection (table 1, examination section 3.1) will be zero where non-existent defects are reported as exceeding the reporting threshold.



#### 4.0 NDT instruction (level 2 only – excluding radiographic interpreter)

The level 2 candidate is required to produce an NDT instruction, suitable for level 1 personnel, for a specimen selected by the examiner. When the level 2 candidate is testing a specimen for which no NDT instruction is required, the grade for that specimen will be calculated as a percentage of the 85 remaining marks.

The marks are awarded against the criteria (4.1 to 4.8 inclusive) specified in Table 1. In order to achieve an examination pass, the candidate must achieve 70%, i.e. 10.5 marks, in section 4 (NDT instruction writing).



#### POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS

#### **METHOD 5.2 – PENETRANT TESTING**

#### 1.1 System control and functional checks

System control and functional checks will usually include predetermined checks, each being allocated a share of the maximum marks (for example, use of test panels; colour, fluorescent intensity and comparator checks of penetrants; concentration checks on developers; efficiency of penetrant removers etc.).

#### 1.2 Verification of equipment settings

Verification of settings will involve the candidate carrying out predetermined checks to give/demonstrate confidence in the ability of the technique to detect discontinuities in the range sought (for example, compatibility of chemicals; pressure of water wash; viewing conditions – white light and UV(A) radiation assessment etc.).

#### 2.1 Preparation of the test piece

Surface preparation.

#### 2.2 Technique selection (level 2)

Selection of the penetrant and developer for optimum sensitivity with due regard to inspection criteria, surface condition and ambient light levels; UV or white light.

#### 2.3 Setting up the NDT apparatus

Avoidance of fire hazards, correct ventilation, safe use of toxic materials and UV(A) radiation.

#### 2.4 Performance of test

Correct application and removal of penetrant; correct use of liquid solvents, aqueous washes and post emulsifiers; correct contact times.

#### 2.5 Post test procedures

Preservation and/or recording of indications; transparent tape transfer and other coating transfers, photographic (fluorescent and colour contrast); cleaning.

#### 3.1 Detection of mandatory reportable defects

Detection of all reportable defects will normally attract maximum marks. However, missing one reportable defect (out of, for instance, a total of three in a specimen) will *normally* attract a mark of zero for detection and a commensurate reduction in



the remaining marks such that the candidate will fail that specimen, since it follows that characterisation, positioning and sizing cannot be carried out for a non-reported defect. A candidate failing one specimen <u>may</u> still achieve at least 70% for the practical part if sufficiently high marks are attained in all other specimens.

Examination centres will provide candidates with a code, specification or standard, or a locally devised instruction on reporting thresholds for each specimen.

#### 3.2 Characterisation

Within the limitations of the NDT method, recording the nature of discontinuity detected (surface and sub-surface where applicable); its position and dimensions.

The candidate is expected to correctly state the nature of the reported indication. Candidate instructions will clarify what is expected in this respect, e.g. whether a simple description (volumetric or planar; crack-like indication) or a fuller description (fatigue crack; lack of sidewall fusion; cold shut; stress corrosion cracking) is required.

The candidate will be expected to accurately report the position of the reported indication with respect to a given datum by giving two dimensions longitudinal and transverse for surface methods and three dimensions length, through thickness and depth for volumetric methods.

Defect dimensions must be correctly reported with the tolerance defined in the master report. The tolerance allowed will depend upon the NDT method/technique and type/position of defect.

#### 3.3 Level 2 evaluation against acceptance criteria

Off-line data analysis procedures for digital/computerised instruments.

Correct interpretation of procedure, code, standard or specification.

#### 3.4 Production of the test report

All pertinent information is reported in writing or as computerised data.

The candidate failing to report a discontinuity specified on the specimen master report as 'mandatory for candidates to report' when performing the test in the conditions specified in the master report will be awarded zero marks for section 3 of the practical examination related to the specimen tested.

<u>Non-reportable defects</u>. The candidate will not be penalised for reporting a non-mandatory reportable discontinuity which does exist in the specimen. However, falsely reporting as a defect an indication which does not actually exceed the reporting threshold will be penalised. Examiners may use discretion in this but, where discretion is applied, the examination must be moderated.

<u>Non-existent defects</u>. The number of marks awarded for detection (table 1, examination section 3.1) will be zero where non-existent defects are reported as exceeding the reporting threshold.



#### 4.0 NDT instruction (level 2 only – excluding radiographic interpreter)

The level 2 candidate is required to produce an NDT instruction, suitable for level 1 personnel, for a specimen selected by the examiner. When the level 2 candidate is testing a specimen for which no NDT instruction is required, the grade for that specimen will be calculated as a percentage of the 85 remaining marks.

The marks are awarded against the criteria (4.1 to 4.8 inclusive) specified in Table 1. In order to achieve an examination pass, the candidate must achieve 70%, i.e. 10.5 marks, in section 4 (NDT instruction writing).



#### POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS

#### **METHOD 5.3 – ULTRASONIC TESTING**

#### 1.1 System control and functional checks

System control and functional checks will usually include predetermined checks, each being allocated a share of the maximum marks (for example, calibration exercise to check flaw detector performance; time base linearity; sensitivity and signal to noise ratio; probe index, beam angle and width, squint, pulse duration etc.).

#### 1.2 Verification of equipment settings

Verification of settings will involve the candidate carrying out predetermined checks to give/demonstrate confidence in the ability of the technique to detect discontinuities in the range sought (for example, sensitivity setting – DAC and/or DGS methods etc.).

#### 2.1 Preparation of the test piece

Assessment of surface condition regularity, choice of couplant, datums and reference points.

#### 2.2 Technique selection (level 2)

Choice of technique related to geometry, size, surface condition, parent metal composition, weld metal structure, taking into account the influence of attenuation in the test piece.

#### 2.3 Setting up the NDT apparatus

Time based calibration for probe angle and test piece geometry; projected distance, shortened projected distance; attenuation correction.

#### 2.4 Performance of test

Correct use of equipment; appropriate scanning patterns; investigation and recording of indications.

#### 2.5 Post test procedures

Equipment care; removal of couplant and restoration of test surface.

#### 3.1 Detection of mandatory reportable defects

Detection of all reportable defects will normally attract maximum marks. However, missing one reportable defect (out of, for instance, a total of three in a specimen) will *normally* attract a mark of zero for detection and a commensurate reduction in



the remaining marks such that the candidate will fail that specimen, since it follows that characterisation, positioning and sizing cannot be carried out for a non-reported defect. A candidate failing one specimen <u>may</u> still achieve at least 70% for the practical part if sufficiently high marks are attained in all other specimens.

Examination centres will provide candidates with a code, specification or standard, or a locally devised instruction on reporting thresholds for each specimen.

#### 3.2 Characterisation

Within the limitations of the NDT method, recording the nature of discontinuity detected (surface and sub-surface where applicable); its position and dimensions.

The candidate is expected to correctly state the nature of the reported indication. Candidate instructions will clarify what is expected in this respect, e.g. whether a simple description (volumetric or planar; crack-like indication) or a fuller description (fatigue crack; lack of sidewall fusion; cold shut; stress corrosion cracking) is required.

The candidate will be expected to accurately report the position of the reported indication with respect to a given datum by giving two dimensions longitudinal and transverse for surface methods and three dimensions length, through thickness and depth for volumetric methods.

Defect dimensions must be correctly reported with the tolerance defined in the master report. The tolerance allowed will depend upon the NDT method/technique and type/position of defect.

#### 3.3 Level 2 evaluation against acceptance criteria

Off-line data analysis procedures for digital/computerised instruments.

Correct interpretation of procedure, code, standard or specification.

#### 3.4 Production of the test report

All pertinent information is reported in writing or as computerised data.

The candidate failing to report a discontinuity specified on the specimen master report as 'mandatory for candidates to report' when performing the test in the conditions specified in the master report will be awarded zero marks for section 3 of the practical examination related to the specimen tested.

<u>Non-reportable defects</u>. The candidate will not be penalised for reporting a non-mandatory reportable discontinuity which does exist in the specimen. However, falsely reporting as a defect an indication which does not actually exceed the reporting threshold will be penalised. Examiners may use discretion in this but, where discretion is applied, the examination must be moderated.

<u>Non-existent defects</u>. The number of marks awarded for detection (table 1, examination section 3.1) will be zero where non-existent defects are reported as exceeding the reporting threshold.



#### 4.0 NDT instruction (level 2 only – excluding radiographic interpreter)

The level 2 candidate is required to produce an NDT instruction, suitable for level 1 personnel, for a specimen selected by the examiner. When the level 2 candidate is testing a specimen for which no NDT instruction is required, the grade for that specimen will be calculated as a percentage of the 85 remaining marks.

The marks are awarded against the criteria (4.1 to 4.8 inclusive) specified in Table 1. In order to achieve an examination pass, the candidate must achieve 70%, i.e. 10.5 marks, in section 4 (NDT instruction writing).



#### POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS

#### **METHOD 5.4 – RADIOGRAPHIC TESTING**

#### 1.1 Detection of mandatory reportable defects

See table 2 for radiographers and radiographic interpreters.

Detection of all reportable defects will normally attract maximum marks. However, missing one reportable defect (out of, for instance, a total of three in a specimen) will *normally* attract a mark of zero for detection and a commensurate reduction in the remaining marks such that the candidate will fail that specimen, since it follows that characterisation, positioning and sizing cannot be carried out for a non-reported defect. A candidate failing one specimen <u>may</u> still achieve at least 70% for the practical part if sufficiently high marks are attained in all other specimens.

Examination centres will provide candidates with a code, specification or standard, or a locally devised instruction on reporting thresholds for each specimen.

#### 1.2 Characterisation

See table 2 for radiographers and radiographic interpreters.

Within the limitations of the NDT method, recording the nature of discontinuity detected (surface and sub-surface where applicable); its position and dimensions.

The candidate is expected to correctly state the nature of the reported indication. Candidate instructions will clarify what is expected in this respect, e.g. whether a simple description (volumetric or planar; crack-like indication) or a fuller description (fatigue crack; lack of sidewall fusion; cold shut; stress corrosion cracking) is required.

The candidate will be expected to accurately report the position of the reported indication with respect to a given datum by giving two dimensions longitudinal and transverse for surface methods and three dimensions length, through thickness and depth for volumetric methods.

Defect dimensions must be correctly reported with the tolerance defined in the master report. The tolerance allowed will depend upon the NDT method/technique and type/position of defect.

#### 1.3 Level 2 evaluation against acceptance criteria

See table 2 for radiographers and radiographic interpreters.

Off-line data analysis procedures for digital/computerised instruments.



Correct interpretation of procedure, code, standard or specification.

#### 1.4 Production of the test report

All pertinent information is reported in writing or as computerised data.

See table 2 for radiographers and radiographic interpreters.

The candidate failing to report a discontinuity specified on the specimen master report as 'mandatory for candidates to report' when performing the test in the conditions specified in the master report will be awarded zero marks for section 3 of the practical examination related to the specimen tested.

<u>Non-reportable defects</u>. The candidate will not be penalised for reporting a non-mandatory reportable discontinuity which does exist in the specimen. However, falsely reporting as a defect an indication which does not actually exceed the reporting threshold will be penalised. Examiners may use discretion in this but, where discretion is applied, the examination must be moderated.

<u>Non-existent defects</u>. The number of marks awarded for detection (table 1, examination section 3.1) will be zero where non-existent defects are reported as exceeding the reporting threshold.

#### 2.0 NDT instruction (level 2 only – excluding radiographic interpreter)

The level 2 candidate is required to produce an NDT instruction, suitable for level 1 personnel, for a specimen selected by the examiner. When the level 2 candidate is testing a specimen for which no NDT instruction is required, the grade for that specimen will be calculated as a percentage of the 85 remaining marks.

The marks are awarded against the criteria (4.1 to 4.8 inclusive) specified in Table 1. In order to achieve an examination pass, the candidate must achieve 70%, i.e. 10.5 marks, in section 4 (NDT instruction writing).



#### POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS

## METHODS 5.5 AND 5.9 – ALTERNATING CURRENT FIELD MEASUREMENT AND EDDY CURRENT TESTING

#### 1.1 System control and functional checks

System control and functional checks will usually include predetermined checks, each being allocated a share of the maximum marks (for example, use of reference standards to provide confidence of detection of defects sought etc.).

#### 1.2 Verification of equipment settings

Verification of settings will involve the candidate carrying out predetermined checks to give/demonstrate confidence in the ability of the technique to detect discontinuities in the range sought (for example, use of calibration blocks for setting sensitivity and reporting thresholds etc.).

#### 2.1 Preparation of the test piece

Surface conditions and preparation – ensuring coatings are uniform and that lift off is within tolerance; marking the area for inspection.

#### 2.2 Technique selection (level 2)

Equipment characteristics and selection; selection of probes and frequency to ensure complete coverage for the application, taking into account the limitations of the test equipment.

#### 2.3 Setting up the NDT apparatus

Training/matching of probe to instrument; lift off compensation.

#### 2.4 Performance of test

Correct use of instrument; probe handling (compensation for coating, edge, geometric and change of conductivity effects, investigation and interpretation of indications.

#### 2.5 Post test procedures

Recording and retrieval of information (on computer/digital instrument, and using written report sheets); marking up of indications; care of equipment.

#### 3.1 Detection of mandatory reportable defects

Detection of all reportable defects will normally attract maximum marks. However, missing one reportable defect (out of, for instance, a total of three in a specimen)



will *normally* attract a mark of zero for detection and a commensurate reduction in the remaining marks such that the candidate will fail that specimen, since it follows that characterisation, positioning and sizing cannot be carried out for a non-reported defect. A candidate failing one specimen <u>may</u> still achieve at least 70% for the practical part if sufficiently high marks are attained in all other specimens.

Examination centres will provide candidates with a code, specification or standard, or a locally devised instruction on reporting thresholds for each specimen.

#### 3.2 Characterisation

Within the limitations of the NDT method, recording the nature of discontinuity detected (surface and sub-surface where applicable); its position and dimensions.

The candidate is expected to correctly state the nature of the reported indication. Candidate instructions will clarify what is expected in this respect, e.g. whether a simple description (volumetric or planar; crack-like indication) or a fuller description (fatigue crack; lack of sidewall fusion; cold shut; stress corrosion cracking) is required.

The candidate will be expected to accurately report the position of the reported indication with respect to a given datum by giving two dimensions longitudinal and transverse for surface methods and three dimensions length, through thickness and depth for volumetric methods.

Defect dimensions must be correctly reported with the tolerance defined in the master report. The tolerance allowed will depend upon the NDT method/technique and type/position of defect.

#### 3.3 Level 2 evaluation against acceptance criteria

Off-line data analysis procedures for digital/computerised instruments.

Correct interpretation of procedure, code, standard or specification.

#### 3.4 Production of the test report

All pertinent information is reported in writing or as computerised data.

The candidate failing to report a discontinuity specified on the specimen master report as 'mandatory for candidates to report' when performing the test in the conditions specified in the master report will be awarded zero marks for section 3 of the practical examination related to the specimen tested.

<u>Non-reportable defects</u>. The candidate will not be penalised for reporting a non-mandatory reportable discontinuity which does exist in the specimen. However, falsely reporting as a defect an indication which does not actually exceed the reporting threshold will be penalised. Examiners may use discretion in this but, where discretion is applied, the examination must be moderated.



<u>Non-existent defects</u>. The number of marks awarded for detection (table 1, examination section 3.1) will be zero where non-existent defects are reported as exceeding the reporting threshold.

#### 4.0 NDT instruction (level 2 only – excluding radiographic interpreter)

The level 2 candidate is required to produce an NDT instruction, suitable for level 1 personnel, for a specimen selected by the examiner. When the level 2 candidate is testing a specimen for which no NDT instruction is required, the grade for that specimen will be calculated as a percentage of the 85 remaining marks.

The marks are awarded against the criteria (4.1 to 4.8 inclusive) specified in Table 1. In order to achieve an examination pass, the candidate must achieve 70%, i.e. 10.5 marks, in section 4 (NDT instruction writing).



#### POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS

#### **METHOD 5.6 – VISUAL TESTING/WELD INSPECTION**

#### 1.1 System control and functional checks

System control and functional checks will usually include predetermined checks, each being allocated a share of the maximum marks (for example, cleanliness and serviceability of optical and lighting equipment etc.).

#### 1.2 Verification of equipment settings

Verification of settings will involve the candidate carrying out predetermined checks to give/demonstrate confidence in the ability of the technique to detect discontinuities in the range sought (for example, calibration of measuring devices etc.).

#### 2.1 Preparation of the test piece

Surface preparation – pre-cleaning.

#### 2.2 Technique selection (level 2)

Selection of most appropriate optical viewing and measuring aids taking into account surface condition, roughness and reflectivity.

#### 2.3 Setting up the NDT apparatus

Measurement of ambient light or of artificial light levels at inspection surface.

#### 2.4 Performance of test

Correct use of equipment; further investigation of indications.

#### 2.5 Post test procedures

Preservation and/or recording of indications – photographic or direct marking.

#### 3.1 Detection of mandatory reportable defects

Detection of all reportable defects will normally attract maximum marks. However, missing one reportable defect (out of, for instance, a total of three in a specimen) will *normally* attract a mark of zero for detection and a commensurate reduction in the remaining marks such that the candidate will fail that specimen, since it follows that characterisation, positioning and sizing cannot be carried out for a non-reported defect. A candidate failing one specimen <u>may</u> still achieve at least 70% for the practical part if sufficiently high marks are attained in all other specimens.



Examination centres will provide candidates with a code, specification or standard, or a locally devised instruction on reporting thresholds for each specimen.

#### 3.2 Characterisation

Within the limitations of the NDT method, recording the nature of discontinuity detected (surface and sub-surface where applicable); its position and dimensions.

The candidate is expected to correctly state the nature of the reported indication. Candidate instructions will clarify what is expected in this respect, e.g. whether a simple description (volumetric or planar; crack-like indication) or a fuller description (fatigue crack; lack of sidewall fusion; cold shut; stress corrosion cracking) is required.

The candidate will be expected to accurately report the position of the reported indication with respect to a given datum by giving two dimensions longitudinal and transverse for surface methods and three dimensions length, through thickness and depth for volumetric methods.

Defect dimensions must be correctly reported with the tolerance defined in the master report. The tolerance allowed will depend upon the NDT method/technique and type/position of defect.

#### 3.3 Level 2 evaluation against acceptance criteria

Off-line data analysis procedures for digital/computerised instruments.

Correct interpretation of procedure, code, standard or specification.

#### 3.4 Production of the test report

All pertinent information is reported in writing or as computerised data.

The candidate failing to report a discontinuity specified on the specimen master report as 'mandatory for candidates to report' when performing the test in the conditions specified in the master report will be awarded zero marks for section 3 of the practical examination related to the specimen tested.

Non-reportable defects. The candidate will not be penalised for reporting a non-mandatory reportable discontinuity which does exist in the specimen. However, falsely reporting as a defect an indication which does not actually exceed the reporting threshold will be penalised. Examiners may use discretion in this but, where discretion is applied, the examination must be moderated.

<u>Non-existent defects</u>. The number of marks awarded for detection (table 1, examination section 3.1) will be zero where non-existent defects are reported as exceeding the reporting threshold.

#### 4.0 NDT instruction (level 2 only – excluding radiographic interpreter)

The level 2 candidate is required to produce an NDT instruction, suitable for level 1 personnel, for a specimen selected by the examiner. When the level 2 candidate is





testing a specimen for which no NDT instruction is required, the grade for that specimen will be calculated as a percentage of the 85 remaining marks.

The marks are awarded against the criteria (4.1 to 4.8 inclusive) specified in Table 1. In order to achieve an examination pass, the candidate must achieve 70%, i.e. 10.5 marks, in section 4 (NDT instruction writing).



#### **POINTS TO BE OBSERVED DURING PRACTICAL EXAMINATIONS**

#### **METHOD 5.7 – TIME OF FLIGHT DIFFRACTION TESTING**

This checklist highlights the control functions expected of the Invigilator involved in PCN TOFD practical exams.

1.0	Data collection:	
	Identify suitable equipment for performing data collection (Refer to list of equipment required for practical examination)	
	Equipment functional check performed (Refer to performance demonstration required as part of the practical examination instruction to candidates )	
	Clear the data collection computer hard drive of all set-up files (Refer to computer hard drive data clearing procedure )	
	Verify correct samples are selected for the candidate	
	Provide blank computer disk for the invigilator to save the candidates examination data on.	
	Provide the candidate with the samples and the Lavender International NDT Ltd instructions to candidate / report form package for data acquisition and monitor the exam.	
	On completion of the data collection section of the practical examination save the candidates data onto disk and delete all data files from the computer hard drive	
2.0	Analysis of data:	
	Clear the test centre computer hard drive of all scan data	
	(Refer to computer hard drive data clearing procedure)	
	Collect the candidates examination portfolio from the Quality Manager & verify the candidate's data analysis portfolio contains a uniquely identified CD containing 5 TOFD data files and the Lavender International NDT Ltd. Instructions to candidate / report forms. The CD shall be identified by the candidate's name and the examination results notice number allocated to that candidate for the examination.	
	Provide the candidate with the portfolio and monitor the examination.	





Retrieve from the candidate the report forms and data CD and return the examination package to the Quality manager for safe storage.	
Clear the test centre computer hard drive of all scan data. (Refer to computer hard drive data clearing procedure)	



#### Extracts from QP4 Sections 7, 17, 22 & 23 for Reference Purposes

#### 7.0 EXAMINATION PROTOCOL

- 7.1 Examiners and Invigilators shall ensure that all examination candidates understand that all written examination papers shall be completed in ink (Blue or Black only). All examination paper marking is to be carried out using Red Ink in order to distinguish between the candidate's work and those comments of any examiner.
  - If, even after the relevant instructions above, any examination candidate mistakenly completes the examination in red ink then examiners shall mark the paper using blue/black ink to ensure there is no confusion should a PCN moderator or assessor audit the examination paper in question. This circumstance must be made very clear on each examination paper.
- 7.2 Candidates are prohibited from using correction fluid and must initial any corrections they make on their exam paper.
- 7.3 Each individual written paper and test specimen report will carry the relevant examination candidate's name and the date of their completion.
- 7.4 All candidates will be issued with the necessary information, codes, standards, examination equipment and materials etc.
- 7.5 TOFD Interpretation examinations:
  - 7.5.1 The TOFD Interpretation examination uses electronic data files transferred to a PC/Laptop by means of a portable USB/memory device.
  - 7.5.2 This data file has a unique identification which shall be written on the candidate's results marking sheet.
  - 7.5.3 All electronic examination files are removed from the portable USB/memory device and shall be deleted from the PC/Lap top (including removal from the recycle bin).
  - 7.5.4 Where possible USB drives are locked during examinations to prevent unwanted transfer of examination material.
- 7.6 Examination candidates shall at all times, during the examination, be closely supervised by a suitably qualified and authorised examiner or invigilator who will ensure that no candidate is permitted an unfair advantage or to collude with other candidates.



- 7.7 Care shall be taken to ensure candidates are not given the same paper or specimens in any subsequent examination.
- 7.8 A notice will be placed in each examination area which prohibits the use of mobile phones, programmable calculators, personal digital equipment with storage facilities unless approved by BINDT (and which if permitted to be used shall be inspected by Lavender International AQB or AEC staff before and after use in an examination). The notice will also inform candidates that the above equipment is barred from written and practical areas and failure to comply with this notice will result in the examination being declared null and void. Lockers are provided in Penistone and at AMP for students to lock away their mobile phones whilst they are undergoing training and examinations.
- 7.9 All invigilators shall ensure that no examination material is removed from the applicable examination room (let alone the Test Centre Premises) by any candidate. This includes any rough notes sketches etc. that the candidate may have made during the examination.
- 7.10 An extension of up to 25% will be allowed in PCN written examinations for candidates suffering from conditions such as dyslexia, or whose first language is not that in which the examination is presented, which may affect their ability to complete PCN examinations in the published time allowed.

A record should be retained with the candidate's folder if an extension of time has been allowed.

Each examination candidate is responsible for bringing their disability (or their other legitimate claims for any extension of examination times etc.) to the attention of Lavender International at the time of their booking and to repeat this to the relevant examiner or invigilator well in advance of the start of any examination.

- 7.11 If necessary an examiner should be present in order to supplement the written examination with oral questions, if necessary, to establish that the candidate has a firm grasp of the topic being examined and to ensure the candidate fully understands the requirements.
- 7.12 All invigilators shall verify the identification of each candidate at point of examination by completing part 1 of PCN form PSL56A.

#### 17.0 INVIGILATORS

17.1 Before any examinations take place Invigilators shall ensure examination facilities are adequate in terms of comfort, lighting etc. and complete the Invigilator check-list on the back of the candidate's exam portfolio.



- 17.2 Invigilation of examinations shall be carried out by persons who have been made fully aware of their responsibilities and duties; and who have received appropriate training as outlined within section 3.12 of this procedure above.
- 17.3 All Invigilators will have access to all examination procedural documentation and applicable records forms.
- 17.4 All authorised Invigilators have been given instruction through the Invigilator Training Programme detailed in Work Instruction WI 09 (or a previous version of this document).
- 17.5 EN4179/NAS410 company-based invigilators are given instruction through WI09A.
- 17.6 All authorised and approved Invigilators are identified on the Company's PCN Schedule of Approvals.
- 17.7 All Invigilators are empowered to ensure that secure examination conditions are maintained at all times and that any infringement of examination conditions by any examination candidate is recorded and immediately reported to the TCCE and/or the PCN Co-ordinator for appropriate action.
- 17.8 PCN Examiners and Invigilators are required, prior to commencement of an examination, to declare any interest in any candidate in whose examination(s) they are involved, in any capacity. An Examiner or Invigilator is prohibited from direct involvement in any examination of a candidate in whom they may have an interest by virtue of:
  - a) Having a common employer within 2 years of the examination date.
  - b) Having provided training in the examination method within 2 years of the examination date.
  - c) Being employed by an organisation which has an interest in the outcome of the examination; and
  - Any other circumstances which may actually or potentially threaten their impartiality.

#### 17.9 Invigilation at Oceaneering

Requests for invigilators at Oceaneering will be made by the Oceaneering Training Course Manager, via email, direct to the Lavender International Admin Manager and copying in the Quality Manager. Such requests should preferably be made at least two weeks in advance. If it is not possible to give two weeks' notice, the request should be made as soon as possible to allow Lavender International time to allocate a suitable invigilator.



# 22.0 <u>ADDITIONAL SPECIFIC EXAMINATION REQUIREMENTS AND RESPONSIBILITIES FOR SNT EXAMINATIONS</u>

#### 22.1 GENERAL

- 22.1.1 This section describes the examination requirements in respect of Companies who have created a Written Practice (Procedure) based on the ASNT Recommended Practice SNT-TC-1A. A number of editions of this document are available and Companies are requested to specify which edition their Written Practice is based upon.
  - 22.1.2 Before the SNT examination candidate attends the Test Centre for examination purposes details of the customer's Written Practice shall be required to be obtained to determine the examination requirements. This will be done by the Quality Manager.
  - 22.1.3 Where no such document exists then Lavender International shall provide full assistance to the employer for the production of this document as examination within the SNT-TC-1A system cannot be carried out without an employer's Written Practice.
  - 22.1.4 In order for the employer to discharge his responsibility with respect to certification to his Written Practice completed examination papers may be returned to the employer on request.
  - 22.1.5 Recertification examinations will be carried out in accordance with the employer's Written Practice.

#### 22.2 THEORY EXAMINATIONS

- 22.2.1 All SNT examination papers shall be written by an approved Company Level 3 and shall show the date and initials of that person. (See QP4 Section 9.2).
- 22.2.2 All papers shall be given a unique reference number and a master list of approved papers shall be held by the Quality Manager.
- 22.2.3 All marking shall be carried out against master answer sheets which carry the same unique number as the question paper and will be retained in the master file with the questions.
- 22.2.4 All SNT examination papers are marked by an appropriate Level 3.



#### 22.3 PRACTICAL EXAMINATIONS

- 22.3.1 All specimens used for SNT examinations are identified on the master specimen list. All specimens are given a unique reference number.
- 23.3.2All specimens for SNT examinations have Master Reports. Each specimen is examined by a person having qualifications of SNT Level 2 minimum in the technique and discipline for the specimen being tested. The Master Report is endorsed and dated by an ASNT Level 3 person approved in the technique being examined.
- 23.3.3 Marking of the examination reports will be carried out by an appropriate ASNT Level 3 person taking due note of the Master Marking Schedule.
- 23.3.4 Examination candidates for Ultrasonic Examination of Welds will be allocated Test Pieces in accordance with (Section 10.11 of this procedure).

## 22.4 <u>SNT RECERTIFICATION BY CONTINUED SATISFACTORY PERFORMANCE</u>

- 22.4.1 It is possible to requalify NDT personnel working to the SNT Scheme on a continuing satisfactory performance basis.
- 22.4.2 The requirements for requalifying on this basis are in accordance with their individual company Written Practice.

# 23.0 <u>ADDITIONAL SPECIFIC EXAMINATION REQUIREMENTS AND</u> RESPONSIBILITIES FOR NAS 410 & EN4179

#### 23.1 GENERAL

- 23.1.1 This section identifies the necessary requirement to meet NAS 410 and EN 4179.
- 23.1.2 Section 22 of this procedure shown above generally describes the administration and general examination requirements that also apply to this section.
- 23.1.3 All examinations will be carried out to the particular requirements described in NAS 410/EN 4179 and the relevant Company Written Practice.

#### 23.2 SPECIFIC EXAM REQUIREMENTS

23.2.1 The relevant Company Written Practice will identify the Prime Certification Specification documents, however this will not capture the



- specific Process Specification which shall be required to be determined by the responsible Level 3 authority and notified to Lavender International.
- 23.2.2 These Process Specifications must be included on form "Exam Requirements for NDT/ME Personnel" (QD 03) to this procedure and shall be signed by the relevant Level 3 Authority.
- 23.2.3 Marking of the examination reports will be carried out by an appropriate NAS410/EN4179 Level 3 person taking due note of the Master Marking Schedule.
- 23.2.4 Examination certificates may only be signed off by an appropriate NAS410/EN4179 Level 3